

W Prager Ltd > Prager Test Site > Prager TS - Manta

Unit Details			
Unit manufacturer	Eureka		
Unit model	Manta		
Asset name / Job ref.	Prager TS - Manta		
Unit serial number	123432		
Unit longitude	-1.39568		
Unit latitude	50.93419		
Unit software version			
General			
Installed by			
Install date	2018-07-10		
Client name	Prager Ltd		
Site name	Prager Test Site		
Region	South West		
Longitude for site	-1.39568		
Latitude for site	50.93419		
Site manager	Ben Simons		
Site telephone no.	01299 888111		
Postcode	SO17 1BJ		
EQuIS code			
Location code (equis)			
Method statement			
Probe details			
Diameter	2.5??		
Power supply	External battery pack		
Cable length (m)			
Output	RS232		
Probe sensors			
Ammonium	yes	Blue-green algae (fresh)	No
Blue-green algae (marine)	yes	CDOM	No
Chloride	No	Chlorophyll a	No
Conductivity / salinity / TDS	No	Crude oil	No
Depth	No	Level / stage	No
Nitrate	No	ORP	No
Optical DO	No	PAR	No
pH	No	Polargraphic D0	No
Rhodamine	No	Sodium	No
TDG	No	Temperature	No
Tryptophan	No	Turbidity	No
Telemetry unit			
Telemetry unit	none		
Flow view Setup Confirmation			
Information loaded on A850?	No		
Co-ordinates in A850?	No		
Addvantage uploaded?	No		
Calibration			
Calibration interval (months)	12		
Next calibration date	Jul 10th, 2019		
Issue Tracking			

Issue No.	56
Category	2 Predicted Instrument Failure < 1 month
Status	● Active
Issue Recorded By	test test
Associated Day Sheets	58 - 6th Aug 2018
Issue Information	Date: Aug 13th, 2018 Admin Name: Chris Turner Issue Information: smple testing
Issue No.	57
Category	3 Poor connectivity - remote investigation
Status	● Active
Issue Recorded By	Chris Turner
Associated Day Sheets	58 - 6th Aug 2018
Issue Information	Date: Aug 10th, 2018 Admin Name: Chris Turner Issue Information: test
Additional files	
Other files	
Notes	
Data input date	Jul 27th, 2018
Inputed by	Chris Turner

Work log

1. Service - 6th Aug 2018	
Day sheet assoc.	Day sheet no. 58 2018-08-06
Reason for visit	Service
Ticket number	
Date raised	Nov 30th, -0001
Reason for callout	
Work carried out	
Items replaced (incl SN)	
New items (incl SN)	
2. Service - 6th Aug 2018	
Day sheet assoc.	Day sheet no. 58 2018-08-06
Reason for visit	Service
Ticket number	54
Date raised	Aug 10th, 2018
Reason for callout	test
Work carried out	
Items replaced (incl SN)	
New items (incl SN)	
3. Service - 6th Aug 2018	
Day sheet assoc.	Day sheet no. 58 2018-08-06
Reason for visit	Service
Ticket number	
Date raised	Nov 30th, -0001
Reason for callout	
Work carried out	
Items replaced (incl SN)	
New items (incl SN)	